


Image Comparison


For Location:

1 Price St, Southport QLD 4215, Australia; -27.96601, 153.40502

Images:


Date: 11.15.2021 / **Time Of Quote**






Date: 11.02.2022 / Time Of Renewal

Marking The Differences





Date: 11.15.2021

Date: 11.15.2021/Zoom

Event Detected

Reroofing

Agenda:

Rust

Debris

Degradation Ponding





Summary of condition changes				
Attributes	11.15.2021	11.02.2022	Change	
Replacement Cost				
Estimated Replacement Cost	\$575,000 AUD	\$619,000 AUD		
Estimated Replacement Cost Per Ft ² :	\$83 AUD	\$89 AUD		
Footprint Area (Ft²)	6,924	6,924		
Construction Type	Masonry	Masonry		
Building Occupancy Type	Car services	Car services		
Facade Material	Brick	Brick		
Gross Floor Area (Ft²)	6,924	6,924		
Estimated Floor Area (Ft²)	5,839	5,839		
Quality Of Finishes	Average	Average		
General Overview				
Number Of Stories	1	1		
Parcel Area (Ft²):	1,265	1,265		



Summary of condition changes				
Attributes	11.15.2021	11.02.2022	Change	
Roof				
Roof Geometry	Shed	Shed		
Roof Material	Corrugated metal	Corrugated metal		
Roof Condition	Poor	Good	Yes	
Roof Condition Score	0.05	0.93		
Roof Geometry Rms Format	2	2		
Number Of Overhanging Trees	1	0		
Area Of Solar Panels On The Roof (Ft²):	0	0		
Facade				
Facade Condition	Good	Good		
Estimated ACP Panels Coverage %	0	0		
Defensible Space				
Number Of Trees On The Parcel:	1	0		
Number Of Trees Within 25 Meters From The Building:	3	2		